FITNESS CERTIFICATE

To be filled by the inspecting Officer (Asst. Engineer) . (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1.	Name of the Officer	OSHNA R
2.	Name of the School	MES COLLEGE Of Engineering Compu School
3.	Location with name of Education District/ Sub, District	Imilianaparom, Edoral Sub pist.
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	RCC Building (Q+3) 14-316 GF- 6.00 x 6.00 x 8.60 - 1, 0/04700 ms 4.88 x 8.88 x 3.60 - 414 1800 m 6.00 x 8.88 x 3.60 - 649/1 Paom 3.10 x 8.40 x 8.60 - 9///ce:
		FF-8.00x 6.00x 3.60 - 5 COSS YOUMS.
5. 6.	Period for which the certificate is issued Nature of defects; if any a) Foundation and basement b) Superstructure c) Doors and Windows d) Wood work wrought and put up e) Roof f) Flooring	SF-18.80 x 6.00 x 3.60 - Seminol tall 6:00 x 18.00 x 3.60 - Compare tall Basement - 6.00 x 6.00 x 3.60 - Activity Reom 6.00 x 8.88 x 3.60 - Stall Room
	g) Miscellaneous (Cracks, etc.)	
7.	Any major defects noticed which will render the building unsafe in any manner	NI
8.	Whether maintenance works have been done properly	Yes
9. I	Whether the structure is sound or not for conducting classes Note: I. The stability of the structure should be examined also exposure of flood etc. 2. Any additional observations if deep	Sound for Conducting Closses ander normal
	separately with this certificate.	new necessity for the certificate may be furnished weomy work
	CERTIFICA	ATE
	certified that the school building was inspected by me or	16/06/2022
four	nd to be fit / unfit to conduct classes, for the period	20.00
·	sons stated above.	
		PRINCIPAL
Plac	e: Thayanur	M.E.S. COLLEGE OF ENGINEERING CAMPUS SCHOOL
	17/06/2023. (Spain)	TRIKKANAPURAM - 679 582 KUTTIPPURAM ASSISTANT INGINEER DAYANKALAMI
in K.6.	M.E.S College of Engineering Campus School Trikkanannyram south Kuttingyram 670 583	1 Assistant Children THAVANOR GRAMIA PRINCER PATE

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer	DSHNP R
2. Name of the School	MES College of Engineering Compan School
3. Location with name of Education District/ Sub. District	Thrilekampurom, Edapal Sub Dist.
 Classification of Building as specified in column 4 of the application for fitness certificate and size. 	RCC Building IB - 315. (9+1)
	GF - 7.00 KG.00 K3.68 - 1 0/055700 m
	5.85× 6.00 × 3.60 - 3 CASUVOOM. 3.80 × 3.45 × 3.60 - SKYTOOM. 7.65× 3.68 × 3.60 - OINNIM.
5. Period for which the certificate is issued 2023 - 2024	FF - 7.00 x 6.00 x 3,65 - 1 (105) 100m
6. Nature of defects; if any	3.85x 6.00 x 3.60 - 3 0055400 m
	3.80 x 3.45 x 3.60 - 310/1 200 m.
a) Foundation and basement	7.65 x 2.68 x 3.60 - Dinning.
b) Superstructure	3.39 x 4.85 x 3.60 - Room.
c) Doors and Windows	
d) Wood work wrought and put up	
e) Roof	
f) Flooring	
g) Miscellaneous (Cracks, etc.)	
Any major defects noticed which will render the building unsafe in any manner	Nil
8. Whether maintenance works have been done properly	yes.
9. Whether the structure is sound or not for conducting classes	Sound for Godenia
Note: 1. The stability of the structure should be examined also exposure of flood etc. 2. Any additional observations if deen separately with this certificate.	Sound for Candacting Classes under norms, with reference to location, altitude, intensity of wind, wind a ned necessary for the certificate may be furnished wather Conditions.
CERTIFICA	A T.
CERTIFICA	<u>ATE</u>
certified that the school building was inspected by me or	16/06/2022
found to be fit / unfit to conduct classes, for the period	allu
reasons stated above.	7025 - 8024 for the
reasons stated above.	T.
State of the state	
Place: Thayonur	ASSISTANDE (
Date: 17/06/2023	RINCTPAL
M. F. S. COOLL. GAN	EGE OF ENGINEERING PUS SCHOOL MOUNTMAN 179.582
Secretary • TRIKKA	Assistant Engineer
M.E.S College of Engineering Campus School Trikkanappuram south Kuttinguram-679 582	ON, THINIMING STAMP PARCHAYADA

PIN: 679 573

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1.	Name of the Officer	ASHNA R.
2.	Name of the School	HES College of Engineering Compas Sch
3.	Location with name of Education District/ Sub. District	Thrilumoperom, Edgal Bab Bola. Oist.
4.	Classification of Building as specified in column 4 of the	Acc Building (6+2) 1x/314
,	application for fitness certificate and size.	0F - 6.00 x 6.00 x 3.60 - 3 classrooms. - G.00 x 6.00 x 3.60 - store room 10.35 x 6.00 x 3.60 - AV Hall
		5.98 x 4.86 x 8.60 - Proyer Holl 6.00 x 5.76 x 8.60 - SICK room
		12.22 x 6.00 x 3.60 - Library
5. 6.	Period for which the certificate is issued 20 Nature of defects : if any a) Foundation and basement	12.22 x G.00 x 3.60 - Chemistry 46 . 4.85 x 2.82 x 3.60 - Room 4.81 x 4 G8 x 8.60 - Room 1.43 x 8.00 x 3.60 - Office Space.
	b) Superstructure	FF- 8.00 x 6.00 x 8.60 - 4 classrooms.
	c) Doors and Windows	10.85 x 6.00 x 3.60 - 0//100
	d) Wood work wrought and put up e) Roof f) Flooring	10.25 x 6.00 x 360 - Principals Cabin 12.22 x 6.00 x 360 - Physics Lab 12.22 x 6.00 x 3.60 - Giology Lob.
	g) Miscellaneous (Cracks, etc.)	SE- 6.00 x 6.00 x 3.60 - 7 Classroom F-00 x 6.00 x 3.60 - Stoffroom.
7.	Any major defects noticed which will render the building unsafe in any manner	10.85 x 6.00 x 8.60 - Moths Lab 5.55 x 6.87 x 3.60 - Prover Mall 5.96 x 3.16 x 3.60 - Otoff 400 m
8.	Whether maintenance works have been done properly	ಶ.
9.	Whether the structure is sound or not for conducting classes. Note: I. The stability of the structure should be examined exposure of flood etc. 2. Any additional observations if separately with this certificate.	d also with reference to location, altitude, intensity of wind, condition
	CERTIF	FICATE
	certified that the school building was inspected by r	me on
fou	and to be fit / unfit to conduct classes, for the period	2023 - 2024 for the
	asons stated above.	
•		
, Dla	ce Thovanur	PRINCIPAL PRINCIPAL PRINCIPAL COLLEGE OF ENGINEERING COLLEGE SCHOOL FOR 582
	ne: 17/06/2023	Seall COLLEGE'S SCHOOL 579 582
-0	10	CONT. CONT.

M.E.S College of Engineering Campus School Trikkanappuram south Kuttippuram-679 582

Assistant Engineer

ASSISTANT ENGINEER . LID & EW SECTION THAVANOOR CRAMA PANCKA STOP